


Scott System #112A Fractured Rope



303-373-2500
10777 East 45th Avenue
Denver, Colorado 80239
www.scottsystem.com
© 2005 Scott System Inc.

Short Form Specification*

Exposed architectural concrete surface treatment shall be obtained with Scott System elastomeric form liner in #112A Fractured Rope as manufactured by Scott System, Inc., 10777 E. 45th Avenue, Denver, CO 80231, 303-373-2500, www.scottsystem.com.

Joints will be tightly butted to prevent leakage. Release agent shall be approved and applied as per Scott System instructions. The liner may be factory bonded at the contractor's option to 1/2" HDO plywood or field-laminated following Scott System's printed directions.

NO SUBSTITUTIONS WILL BE ALLOWED WITHOUT PRIOR WRITTEN APPROVAL FROM THE PROJECT ARCHITECT OR ENGINEER.

* Note: Please refer to our full specification and installation instructions for complete details about our Flex-Liner™ product.